



Certification of Compliance

Product Identification

Product Description: Telescoping 3/4# Magnetic Pick Up

Part Number: MI8822

Purchase Order Number: Varies

Testing Information for Compliance with Regulations

Regulation:	Test Facility/Location:	Date Tested:
CPSIA Section 101, Total Lead in Substrate Material – Test #21W-003569	QIMA & AsiaInspection, Hangzhou, China	4.27.21
CA Prop 65, Total Lead in Substrate Materials – Test #21W-003569	QIMA & AsiaInspection, Hangzhou, China	4.27.21

U.S. Importer or Domestic Manufacturer Certifying Compliance

Fey Promo
200 4th Ave N
Edgerton, MN 56128

Contact Information for Custodian of Test Records

Compliance Manager Mi Line by Fey 200 4 th Ave N Edgerton, MN 56128	Ph. (507) 442-4311
---	--------------------

Date and Place Where Product was Manufactured

Date:	Daily
City and Country:	Edgerton, MN

Third Party Testing Laboratories on Which Certificate is Based

Hangzhou AsiaInspection Testing Technology Co., LTD 5/F A2 Building, No. 1213 Huoju South Road, Puyan Street, Binjiang District, Hangzhou, China	QIMA Testing (HK) Limited 3/F Liven House, No. 61-63 KingYip Street, Kwun Tong, Kowloon, Hong Kong	QIMA (Hangzhou) Testing Co., LTD 4-5/F A2 Building, No. 1213 Huoju South Road, Puyan Street, Binjiang District, Hangzhou, China
--	---	---